

RENEWAL

523 | 524
526 | 525

T325 RBW

FOUND 1 BT

40" D FIR Now 52" N50E 19°

SHOWS BARK SCIBE OF (S, 2 BT)

40" D FIR Now 26" S30E 21°

SHOWS NO SCRIBING

NOTE NO TRACE OF S, W, E N, W, BT'S

SET BRASS CAP AT CORNER MKD.

COUNTY SURVEYORS OFFICE

T325 RBW

523 | 524
526 | 525
1968

RESKRIBED, BT!

52" D FIR N50E 19° (BARK SCRIBED)
SCRIBED (T325 RBW 524 CS BT)

NEW BT'S.

10" D FIR S26W 45°

SCRIBED (T325 RBW 526 CS BT)

24" D FIR S85E 47°

SCRIBED (T325 RBW 525 CS BT)

NOTE. NO TREES IN RANGE FOR

SCRIBING IN N, WEST. NOTE CREEK IS

360° NORTH OF THIS CORNER. 4-15-68

DIETZGEN NO. 385-6

712

O.K. J. W.

C.S.

PRO NO.

54/65-305