

Renewal

31/32

T325 RBW

Found:

36" D Fir Now 25" stub  
old fire work

N80W 15<sup>E</sup>

22" D Fir Now 36"  
old fire work.

S50E 47<sup>E</sup>

Found no scribeing, however both trees  
are approx size and good bearings & Dist  
Also call at creek of 1 chain  
South bits very good.  
old scribed post at cor point  
not at record, this cor also used since  
1943 Forest location tag.  
Finding trees & call to match notes  
I renew.

Set Brass cap at 1/4 cor MKD

county Surveyors office

T325 RBW

1/4 S31/332

1968

New Bearing Tree

12" D Fir  
Scribed

N63W

11<sup>E</sup>

1/4 S31 CS BT

Relaxed & Rescribed

36" D. Fir  
Scribed

S50E

77<sup>E</sup>

1/4 S32 CS BT

5-3-68

*[Handwritten signature]*

#78 O.K. J.W.O.

C. S. File No. 5465-416

DIETZGEN NO. 3886-6