

Renewal

32 only T325 RBW

Found

10x8x4 Stone at $\frac{1}{4}$ cor MAR. $\frac{1}{4}$ on
The north face.

8" D. Fir Now 5 1/2" N9E 3 1/2"
Scribed inside

1 1/2" D. Fir Now 2" N99E 1 1/2"
Shows good seam.

Renewal

Set Brass cap at $\frac{1}{4}$ cor MAR.

County Surveyors Office
Doug. Co
T325 RBW

S32

Jasp. Co.
T333

1968

New Bearing Tree:

8" D. Fir N18E 6"
Scribed $\frac{1}{4}$ S 32 SC CS RT

Notes: This cor lies on steep
North slope approx 125° East
of draw NE-SW

5-6-68

~~J. W. G.~~
~~J. W. G.~~
~~J. W. G.~~

D. K. J. W. G.

C. S. File No. 54/65-59

DIETZGEN NO. 385-B