

Renewal

33 | 34
3

7325
7335

2
10
11

Found:

16 X 14 Y 9 Stake at Sec cor 3 Grooves
on E & W sides

24" D.Fir Now 32" N 71 E (Pac NW SE) 35°
All Bark Scribe Gone

16" D.Fir Now 24" N 98 W 13°
Bark Scribe Visible "8 W" "13"

Also:

34" D.Fir Now 40" S 26 W 7°
This Tree Supposedly Destroyed Shows
Faint Bark Scribe "S 4" "7335"

Renewal

Set Brass cap at sec cor N 1/4
County Surveyors office

Doug Co
7325 RBW

533 | 534

53

7335

Jos. Co
1968

New Bearing Tree

9" Laurel N 10 E 35°
scribed 7325 RBW 534 SC CS BT

Relaxed & Rescribed

29" D. Fir N 48 W 13°
scribed 7325 RBW 533 SC CS BT

579-68
2223
7335

85

D. K. J. W. B.

C. S. File No.

5465-11

DIETZGEN NO. 385-6