

Reverend

SS

T315
T325 RIW

Found

3/4" I Pipe

This 3/4" I Pipe pro. rated in
by Deland P. Lovejoy #262

No Trees set.

Map in File 71/159

DIETZEN NO. 388.6

New Bearing Trees

6" W. F. r

Set. 1/4 S 55°

S 28 E

60 BT

191

7" W. F. r

Set. 1/4 S 55°

S 38 W

65 BT

164

Note

This cor. lies at Fence cor., Fence
Bearing East & South. Also 1592
West of SE cor Sec. 32
T315 RIW

7-22-68

[Handwritten signature]

#57-231-1

#19

O.K. J.W.

C.S. File No. 54/28