

General

531

ONLY T315 R1W

Found:

30" D. Fir. Now 36" N50E 17^B
Shows good Scar with points of
Scribing visible Also faint Bark
Scribe $\frac{1}{4}$ S BT

Cor Tree $\frac{1}{4}$ SE BT Down &
out of place. A lot of trees
fall out of the snow bank &
slid down Mountain

General

Sad Brass cap at 4 cor. 172 D

County Surveyors office

T 315 R1W

531 $\frac{1}{4}$

T 315 R2W

1968

New Bearing Tree

18" D. Fir N21 E 55^B
Scribed $\frac{1}{4}$ S31 CS BT

Note:

This cor lies 15^B West
of $\frac{1}{76}$ T315
T325 R2-1W.

7-21-68

[Handwritten signature]

54-531-1

522 O.K. J.W. 13.

C.S. File No. 54/222

DIETZGEN NO. 385-6