

Renewal
(Renewal #5)
Found:

$\frac{9}{16}$

T325 81W

21" Cedar Now 26" N63 $\frac{1}{2}$ E 21°
Scribe visible $\frac{1}{4}$ 59 BT
No Trace of SW Tree or
stone
south of line old logging.

Renewal

Set Brass cap at $\frac{1}{4}$ cor 14 RD.
county Surveyors office
T325 R1W

$\frac{1}{4}$ $\frac{59}{316}$
1968

New Bearing Tree.

13" Double Maple S50 $\frac{1}{2}$ E 925°
Scribed $\frac{1}{4}$ 316 25 BT

Note:

This cap lies about 190°
East of Small Spring Branch.

8-9-68

#45-31-1

1 O.K. J.W.B.

C.S. File No. 54/71-33