

Renewal

37/35

T31

T32

R/W

Found

(Renewal #1)

T31-1

12" Maple

Now 14 1/2" W

16 5

Scribe visible

39 BT

6" Maple

Now 20" N64E

37 5

Butt cut face BT visible

6" Maple

Now 6" N34W

26 1/2

opened & rotten

20' Fir SW Not found.

Also found of stone cut cor

Renewal

Set Brass cap at sec cor. 1947

county Surveyors office

T31S81W

534 | 535

53

T32S

1968

Redwood & Rescribed

10" Maple

~~N64E~~

39 5

Scribe

T31S R/W 535 CS BT

New Bearing Tree

24" d. Fir

S79 W

36 5

Scribed

T32S R/W 53 CS BT

Note

This cor lies in bottom of
Draw

8-16-68

[Signature]

T32-1

1950
368

W. K. J. W. S.

C. S. File No.

5471-AX

DIETZGEN N. D. 385-B