

Renewal $\frac{1}{4}$ 528 | 527 T31S R1W

Found

10" FIR CORNER TREE WHICH IS NOW 14"

SHOWS 2 GOOD FACES

18" FIR NOW 22" WINDFALL S15E 113

SHOWS GOOD FACES

22" FIR NOW 22" WINDFALL S65W 113

SHOWS SCRIBING OF $\frac{1}{4}$ 528 BT

Renewal

SET BRASS CAP AT $\frac{1}{4}$ COR. ON SOUTH SIDE OF

THE CORNER TREE AND MKD.

COUNTY SURVEYORS OFFICE

T31S R1W

$\frac{1}{4}$ 528 | 527

1968

New BS

6" DFIR S30W 6"

SCRIBED $\frac{1}{4}$ 528 CS BT

10" WFIR SSE 35'

SCRIBED $\frac{1}{4}$ 527 CS BT

NOTE: THIS $\frac{1}{4}$ COR LIES IN A N/E CUT

TINA CORNER.

Handwritten signature

7-26-68
JMP
FWJ

#126 O.K. J.W.B.

W.R.D. JR.
C.S. File No. 54171-59

DIETZGEN NO. 385-B