

Renewal

28/27
33/34

T31S R1W

Found:

28" D. Fir now 38" N81E 35 1/2
Shows good Scar

14" Maple now 16" S31E 31 1/2
Shows Scar

30" D. Fir now Stump N11W 20 1/2
Shows good Scar

No Trace of F SW BT.

Brass cap MKD.

General Land Office

T31S R1W

528/527
533/534

1922

(Cap out of ground)

Renewal:

Reset Brass cap at sec cor.

New Bearing Trees

16" D. Fir N68W 17 1/2
Scribed T31S R1W 528 CS BT

13" Hemlock S15W 51 1/2
Scribed T31S R1W 533 CS BT

9-26-68

JWD
MJB
JWB

#125 O.K. J.W.B.

U.S. File No. 54/71-60

DIETZEN NO. 385-6