

Renewal $\frac{1}{4}$ 519/520 T315R1W
Renewal # 6

Found: Two ORIG. BT as described by G.L.O.
field notes. Plus The Renewed BTs by
Robert Thompson in 1956.

ORIG. 40" S Pine now 44" windfall N 47 E 26¹/₂ FT ORIG
Shows good scribings of (1/4 S BT

18" oak now 26" snag 528 w 11¹/₂ FT ORIG.
Shows a Poor face

16" D FIR now 18" N 19° 40' W 17¹/₂ N, BT.

Shows good scribings of (1/4 S 19 42/252 BT)

16" D FIR now 18" S 48° 10' E 17¹/₂ FT N, BT

Shows good scribings of (1/4 S 206 Part of BT)

Set Brass cap 1/4 cor mark.

COUNTY SURVEYORS OFFICE

T315 R1W

$\frac{1}{4}$ 519/520

1968

NOTE: This 1/4 cor lies on a gen. East
slope.

9-30-68

W.R.P. JR.

W.M.P.
East
W.R.P. JR.

DIETZEN NO. 385-6