

Renewal 27/26 T315 RIW

Found:

Brass cap MAD

General load office

T315 RIW

527/526

1922

Said cap out of ground on steep west slope.

8" D. Fir Now 15" N11E 185°
Slope's good bear

4" D. Fir Now 9" N36W 85°
opened for scribe 18°

Renewal

Reset Brass cap at $\frac{1}{2}$ cor in mound of stone

New Bearing Tree

7" D. Fir N61E 45°
scribed N527 CS 87

B-30.68

[Signature]
B-30.68

D.V. J.V. B.

DIETZGEN NO. 385-B