

Renewal 15/19 T31S R1W

Found:

Brass cap at 1/4 cor MKD.

General land office

T31S R1W

1/4
S15/S14

1922

24" D. Fir Now stump S37E 8⁶
shows good scar

30" D. Fir Now stump S45W 8⁶
Scribe visible "BT"

Renewal

New Bearing Trees

11" R. Fir N 23 E 19°
scribed 1/4 S14 CS BT

13" Hemlock N 71 W 36°
scribed 1/4 S15 CS BT

9-9-68

#97 D. V. J. W. B.

C. S. File No. 54/71-28

DIETZGEN NO. 385-6