

Renewal / 518 T315 RIW E

Found

Brass cap at $\frac{1}{4}$ cor MKD

General land office

T315

N	/	1	B
1	518	1	
W			E

1922

5" Hemlock now down N93E 17°

5" Chingumpin now 8" S51E (271) 24°
Scribe visible 518 BT
Rotten Fall

Renewal

New Bearing Trees

6" Hemlock N39E 10°
Scribed $\frac{1}{4}$ 518 CS BT

5" Maple S72E 13°
Scribed $\frac{1}{4}$ 518 CS BT

Note This cor lies on tip of
Ridge running approx S72E &
approx 12° south of creek

OK, J.V.V.B.

#105

C.S. File No. 54/71-134