

Renewal 513/only T315 RIW-15

Founds:

5x10x5 stone at $\frac{1}{4}$ cor MKD,
 $\frac{1}{4}$ W Face

48" D Fir now snag N2.W 1/6^e
shows good Saax.

40" D Fir now snag S.22W 1/1 F
shows good Saax.

Also Remains of cedar 570E 15^z
which was destroyed

Renewal

Set Brass cap at $\frac{1}{4}$ cor MKD
County Surveyors office

T315

R	513/	R
W	$\frac{1}{4}$	E
	1968	

New Bearing Trees

9" D. Fir N1W 13^z
scribed $\frac{1}{4}$ S13^z cor BT

8" D. Fir S83W 9^z
scribed $\frac{1}{4}$ S13^z cor BT

9-16-68

[Handwritten signature]

#108

G.S. File No. 54/71-137

DIETZGEN NO. 385-6