

Renew E. 1/4 517 | T255 R8W

Ed. O.B.T. as follows -

orig 10" now 14" cedar N. 45° W. 34 3/4 ft.

Turned out - scribe MKs. visible on  
open Bl/22. For Bearing & Dist.  
we use center of hole where

cedar stood. we find only traces  
of Fir Log - no scribe in approx.  
location of B.T. to west. at cor.

point as determined from location  
of cedar B.T. set 1" I.P. & Brass cap  
MKd. COUNTY SURVEYORS OFFICE

1968 T255 1/4 517 | R8W" & MK

New B.T.s -

6" Hemlock N. 71° W. 9 1/2 ft.

Mkd. " 1/4 517 CS BT "

13" Hemlock S. 24° W. 13 7/8 ft.

Mkd. " 1/4 517 CS BT "

This cor. lies on steep northerly  
slope - The West 1/4 cor. of

sec. 16 bears N. 12° E. 187 1/2 ft.

Not agreeing with record bearing & dist.  
of N. 0° 02' W. 208 1/2 ft.

August 1, 1968

#43 J. W. Tracy

V.R.T.

J.H.

V.P.

D.N. J. W. B.

C.S. File No. 54/72-13