

Renew $\frac{1}{4}$ $\frac{512}{513}$ T265 R8W

Fd. O.B.T.s as follows -

Orig. 18" Now 33" FIR N, 62° W, 10⁶ ft.

2 live - find $\frac{1}{4}$ " BARK scribe in poor cond.

Orig. 20" Now 42" ^{FIR} N.S. 68° W, 6⁶ ft.

Record, N, 68° E, - 2 live - shows "B" BARK scribe in poor cond. upper eye blaze chopped off. previously at cor. point set 1" I.P. & BRASS CAP MKD.

"COUNTY SURVEYORS OFFICE 1968

T265 $\frac{1}{4}$ $\frac{512}{513}$ R8W" & MK. New B.T.s

30" D. FIR N, 4° W, 6⁸ ft.

Mkd. "4512 CS BT"

42" D. FIR S, 68° W, 6⁶ ft. (O.B.T.)

Mkd. "4513 CS BT"

This cor. lies on top of ridge course E. & W.

August 23, 1968

V.R.T.
F.J.
V.P.

V.R. Tray

O.K. J.W.B.

#32

C.S. File No. 54/72-19