

Renew Sec. Cor. $\frac{511}{514} \frac{512}{513}$ T265 R8W

Fd. O.B.T.s as follows -

Orig. 6" Now 14" Hemlock N. 52° E. 17 $\frac{1}{2}$ ft.

2 live - scribe visible on open blaze.

Orig. 30" Now 40" Fir S. 60° E. 37 $\frac{0}{10}$ ft.

2 live - shows good scars.

Orig. 16" Now 24" Chinquapin S. 56° W. 39 $\frac{6}{10}$ ft.

Record S. 60° W. 37 $\frac{0}{10}$ ft apparently Bearing

& Dist. Turned around. 2 live scribe

visible on nearly healed blaze - poor

No trace NW O.B.T. - 2nd cor. point

set 1" I.P. & Brass cap MKd "COUNTY

SURVEYORS OFFICE 1968 T265

$\frac{511}{514} \frac{512}{513}$ R8W " & MK. New B.T.s -

18" Hemlock S. 58° E. 32 $\frac{8}{10}$ ft.

Mkd. "T265 R8W 513 CS BT"

17" Hemlock N. 17° E. 27 $\frac{0}{10}$ ft.

Mkd. "T265 R8W 512 CS BT"

5" D. Fir N. 74° W. 17 $\frac{6}{10}$ ft.

Mkd. "511 CS BT"

24" Chinquapin S. 56° W. 39 $\frac{6}{10}$ ft.

Mkd. "T265 R8W 514 CS BT" (O.B.T.)

This cor lies on top of Mtn. in

Dense Rhododendron Thicket.

Sept 16 1968

STW R Tray

U.R.T.

J.H.

U.P.

C.S. File No.

54/72-27

OK
JTW/AB