

533/534 T255

Renew Sec. Cor. 54/53 T265 R8W

Fd. C.B.T.s 25 follows -

orig. 15" now 30" cedar S 85° E, 2 1/2 ft.

alive - Leaning Badly - faint scar.

orig. 20" now 36" cedar S. 40° W, 3 3/4 ft.

Record S. 40° E, - now 8 ft high S N of we  
open & find Reverse scribe "B"

orig. 12" now 22" cedar N. 88° W, 5 3/4 ft.

alive - shows faint scar - we Rescribe

"T255 R8W 533 CS BT" No Tree

Maple C.B.T. To N.E. - at cor point

set 1" I.P. & Brass cap MKd. COUNTY

SURVEYORS OFFICE 1968 T255

533/534  
54/53

T265 R8W " & MK New BTs -

60" D. Fir S. 25° E, 30 1/2 ft.

Mkd. "T265 R8W 53 CS BT"

26" Hemlock S. 16° W, 32 1/2 ft.

Mkd. "T265 R8W 54 CS BT"

8" Hemlock N. 41° E, 21 1/2 ft.

Mkd. "T255 R8W 534 CS BT"

This cor. lies on very steep  
west slope approx 150 ft. East  
of Bench.

Sept 26, 1968

URT  
J.H.  
V.P.

*[Signature]*

C.S. File No.

54/72 K. 32

J.V.V.B.