

Renew  $\frac{1}{4}$   $\frac{536}{51}$  T255 R8W

Fd. o.B.T. as follows -

ORIG. 30" Now 48" FIR S. 35° E. 26  $\frac{1}{2}$  Ft.

Now STUMP - only small TRACE of

BARK SCRIBE Remains - CRUISERS

MARKS "  $\frac{1}{4}$  R HB " & Yellow Tag on SE. BT

Recorded in Forrest appraisal survey  
Dated Nov. 1951 by Lecliden & Givenis.

we find NO TRACE of old NE. BT. -

at COR. point set 1" I.P. & BRASS cap  
MKd. " COUNTY SURVEYOR'S OFFICE

1968 T255  $\frac{1}{4}$   $\frac{536}{51}$  T265 R8W " &

MK. New BTs -

14" Hemlock S. 68° W. 50  $\frac{1}{2}$  Ft.

MKd. "  $\frac{1}{4}$  51 CS BT "

10" cedar N. 87° E. 28  $\frac{1}{2}$  Ft.

MKd. "  $\frac{1}{4}$  536 CS BT "

This COR. Lies on very steep  
North slope approx 100 ft. South  
of creek course East. we  
put Yellow Line Tag at creek  
Approx 100 ft. N. of COR.

Sept 26, 1968

*J.P. Tracy*

V.R.T.

J.H.

V.P.

54/22-33

J.W.H.S.

C.S. File No.

39-726-8