

Review  $\frac{1}{4}$   $\frac{527}{534}$  T265 R8W

Fd. O.B.T.S. 05 follows -

Orig. 72" Now 74" Fir S,  $24^{\circ}$ W, 30 $\frac{1}{2}$ ft.

Now SNG - OPEN & shows SCRIBE MKS.

Orig. 36" Now 44" Fir N,  $26^{\circ}$ W, 56 $\frac{1}{2}$ ft.

Now Decayed Stump - NO SCRIBE Fd -

Note: we MEASURE FROM Face of O.B.T.S.

at cor. point set 1" I.P. & BRASS

cap MKd. "COUNTY SURVEYORS

OFFICE 1970 T265  $\frac{1}{4}$   $\frac{527}{534}$  R8W"

& MK. New B.T.S. -

14" D. Fir N,  $67^{\circ}$ E, 21 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$  527 CS BT"

15" D. Fir S,  $7^{\circ}$ E, 7 $\frac{3}{4}$ ft.

Mkd. " $\frac{1}{4}$  534 CS BT"

This cor. Lies on Nearly flat  
southerly slope. There is

3 Weyerhaeuser Co. Tsg on a

14" Fir N,  $28^{\circ}$ W, 27 $\frac{1}{2}$ ft. No

"W" Fd. - see also C.S. 18/55 -

July 14, 1970

V.R.T.  
V.D.P.  
J.W.B.

J.R. Tracy

#44

C.S. File No.

54/72-<sup>5</sup>16

S.K.  
J.W.B.