

Renewal

~~37~~
773

7295
7305 R2W

Found

5" Cedar (OBT) NW 56⁶ S 89³ W 32³

No trace of SE BT

Also 48" Car Tree NW 56" shows
good scars.

Renewal

Set Brass cap on South side of
Car Tree M50

County Surveyors office

7295 R2W

~~37~~
54/53

7305 R2W

1968

DIETZGEN NO. 385-6

New Bearing Traces

6" Cedar S 82¹ E 17⁰
Scribed T. 305 R2W S3 CS BT

8" Red Fir S 64¹ W 16²
Scribed T. 305 R2W S4 CS BT

9" W. Fir N 80¹ E 7²
Scribed T. 299 R2W S44 CS BT

Note: This cor lies 26⁰ East of ~~12/34~~

10-14-68

#25-T29-2 O. V. J. W. B.

#208-T30-2

C. S. File No. 54/732