

Renewal

18/17  
19/20

T30S R2W

Found.

15x8x6 Stone at Sec cor No  
Notches as described visible

12" D. Fir Now Down & Rotten N72 $\frac{1}{2}$ E 6 $\frac{1}{2}$   
Found Scribing R2W

12" D. Fir Now 16" S22 $\frac{1}{2}$ E 7 $\frac{1}{2}$   
Shows good Scar

10" D. Fir Now Stump N71 $\frac{1}{2}$ W 33 $\frac{1}{2}$   
Shows good Scar

15" Laurel Now 23" S32W 23 $\frac{1}{2}$   
Shows Faint Scar

Renewal

Set Brass cap at Sec cor MTR  
County Surveyors office

T30S R2W

518 | 517  
519 | 520

1968

New Bearing Trees

18" D. Fir N49 $^{\circ}$  E 15 $\frac{1}{2}$   
Scribed T30S R2W S17 CS 27

7" Hemlock N23 $^{\circ}$  W 34 $\frac{1}{2}$   
Scribed T30S R2W S18 CS 27

Note This carries directly on top of  
Large Ridge Burial E-W

10-22-18

D. W. J. W. 19

#118

C. S. File No. 54/23-10

DIETZGEN NO. 385-6