

Reverend (#10) S32 T30S R2W

Found:

Stone at $\frac{1}{4}$ cor MKD with an X
 20" D. Fir New Stump S5E 21⁺
 Scribe visible "BT"
 12" D. Fir New Stump S84E 21³
 Scribe visible "BT"

Reverend

Set Brass cap at $\frac{1}{4}$ cor MKD
 county Surveyors office
 T30S R2W

$\frac{1}{4}$ S32
 1968

DIETZEN NO. 385-6

New Bearing Trees

8" D. Fir S76W 37[±]
 Scribed $\frac{1}{4}$ S32 CS BT
 9" D. Fir S50E 11[±]
 Scribed $\frac{1}{4}$ S32 CS BT

Note:

This cor lies 29° East of.
 $\frac{1}{4}$ S29

11-1-68

[Signature]
 1036

1038-T30-2 O.H. J.W.B.

C.S. File No. 54/73-22