

Reverend

535

T295 P2W
T305 P2W

Found:

15" D. Fir now 22" N. 56 1/2 E 45°
shows good Scar

15" W. Fir now 22" N. 51 W 35°
opened for scribing 115°

No trace of 1917 Brass cap
as car falls in cut for
old S.A. Rd. which comes
directly down Sec. line.

Reverend

Set Brass cap at 1/4 cor MND
county Surveyors office

T295 P2W

530

T305

1968

All BTs OK & Tagged

Note:

11-6-68

This cap 7' x 39"
West of 1/4 52 T305 P2W

[Handwritten signature]

D.W. J.W.B.

30-729-2

#10-T305

C.S. File No. 54/79-24

DIETZEN NO. 388-6