

Renewal # 58 $\frac{21}{28} \frac{22}{27}$ T303 R2W

Found:

16" B. Oak N 41 1/2 W 13 1/2
Shows good scar (D.B.T.S.)

New Bearing Trees:

16" D. Fir N 70 3/4 E 16 9
Dist to Rail (Dist to center 47 1/2)
Pitched over scribe visible

22" D. Fir N 41 22" S 55 W 31 3/4
Dist to Rail (Dist to center 35 1/2)
Pitched over scribe visible.

8" D. Fir N 41 10" S 64 E 20 3/4
Shows good scar.

Also stone firmly at sec cor.
MKA with grooves.

Renewal

Set Brass cap at Sec cor MKA
county Surveyors office

T303 R2W

$\frac{521}{528} \frac{522}{527}$

1968

All Bearing Trees ok
T303

11-27-68
[Signature]

D.V. J. Co.

DIETZEN NO. 385-6