

Renewal

27/26  
37/35

T302 R2W

Found:

15" S. Pine New 20" S@W 285°  
Some visible T302 R2W S27  
BT Scar (Tree exposed)

15" Fir New stump shows good scar N@W 35°  
No trace of NE or SE BT.

Renewal

Set Brass cap at see cor MKD.

county Surveyors office

T302 R2W

S27 1526  
S27 1530

1968

New Bearing Trees

19" S Pine N 5 W 94°  
Scribed T302 R2W S27 CS BT

12" D Fir N 2 E 103°  
Scribed T302 R2W S26 CS BT

14" D Fir S@E 74°  
Scribed T302 R2W S30° CS BT

Note:

This cor lies 15° South of

Tel. Phone line running NE-SW

12-3-68

DIETZEN NO. 3886-S

#158

O.K. H.W.B.

C.S. File No. 54/73-59