

Renewal

$\frac{16}{21}$

T30S R2W

Found:

18" Fir cor Tree now 30" shows good  
scars

21" Fir now stump N47 $\frac{1}{2}$ W 41 $\frac{1}{2}$   
shows scars

36" cedar now stump S66 $\frac{1}{2}$ W 49 $\frac{1}{2}$   
Tree opened scribe visible  $\frac{1}{2}$ S

Renewal

Set Brass on south-west side of cor  
Tree MRP

County Surveyors office

T30S R2W

$\frac{1}{4}$   $\frac{216}{321}$

1968

New Bearing Tree

17" D. Fir  
Scribed  $\frac{1}{4}$  S16 CS 87 N20W 25 $\frac{1}{2}$

16" D. Fir  
Scribed  $\frac{1}{4}$  S21 CS 87 S5E 33 $\frac{1}{2}$

12-5-68

*[Signature]*

O.K. 5 W.B.

#169

C.S. File No. 54/75-64

DIETZGEN NO. 388-6