

Renewal

17/16

T295 R/W

Found:

12" Hemlock down rotten S45W 23¹
found definite scribe marks.

No trace of SE BT.

Also found old ax BT stump N71W 32³
which was destroyed but found
scribing on all face

No trace of stake.

Renewal:

Set Brass cap at sec cor MKD,
county surveyors office

T295 R/W

59
517/516

1969

New Bearing Trees

6" Hemlock S81W 20⁶
scribed T295 R/W 517 CS BT

6" Hemlock S71¹/₂E 7⁹
scribed T295 R/W 516 CS BT

14" Cedar N17W 33²
scribed T295 R/W 59 CS BT

Note: This cor lies 103¹/₂
East of 819
17

1-21-69

[Handwritten signature]

D.K.
J.W.B.

C.S. File No. 54/82-19

DIETZEN NO. 385-6

#36