

Renewal

513/only

T295 R2-1W

Found

19<sup>±</sup>

10" D. Fir diam 24" SW 1/4 19<sup>±</sup> (Rec 86<sup>±</sup>)  
Shows good scar

10" D. Fir diam 34" N 80 W 19<sup>±</sup>  
Shows faint scar

Also Brass cap at 1/4 cor MKD.

General land office

1/4

513/

1917

New Bearing Tree

22" R. Fir 1/2 112 W 37<sup>±</sup>  
scribed 1/4 513 CS BT

Reblazed & Re scribed

34" D. Fir N 80 W 19<sup>±</sup>  
scribed 1/4 513 CS BT

Note

This cor lies 13<sup>±</sup> North of 1/4 518

5-1-69

OK  
1/4 W 1/4

DIETZGEN NO. 385-6

69 #54 2W

C.S. File No. 54/82-44