

Renewal

20 | 21 T295 RIW
29 | 28

Found no TRACE of 18X12X10 CORNER STONE,
because THE CORNER falls in a old SKID ROAD.

Found Two Good BEARING TREES.

8" CEDAR now 22" S50W 47 1/2 FT

Shows, Good SCRIBE OF (T2, R₁)

14" R FIR now 32" N81W 53 1/2 FT

Show, Good face

10" R FIR now 28" STUMP N50E 151 1/2 FT

CUT TO LOW TO SHOW FACE OR SCRIBING

24" R FIR now 42" STUMP S75E 118 1/2 FT

Shows SCRIBE OF a (W)

SET BRASS CAP AT SEC. COR. FROM BEARING
and DIST. FROM BEARING TREES. (MKD)

COUNTY SURVEYORS OFFICE

T295 RIW

520 | 521
527 | 528
1969

NEW BEARING TREES:

6" D N52E E 23 1/2 FT

SCRIBED: (T295 RIW S21CSBT)

14" D FIR S55 E 23 1/2 FT

SCRIBED: (T295 RIW S28CSBT)

NOTE: THIS COR. LIES IN A SKID ROAD ON TOP

A RIDGE WITH LOGGED UNIT TO THE EAST.

1/5 1/2 1920 S. File No. 545/1469 F.W.J. WR.RJR. - 63

DIETZGEN NO. 385-6

D.H.
J.W.H.A.