

Renewal

1/4 S24

T295 R1W

Found: no Trace of 4x10x8 corner stone

Found one good bearing tree

24" FIR 30 now S48W 2.2<sup>th</sup> old BT

Shows good scribe of (1/4 S24 BT)

14 Fir now 20 N65W 337 FT New BT

Shows a good face

Set Brass cap at 4 cor from bearing  
and dist from

COUNTY SURVEYORS OFFICE

R 2275 R

1/4 S24 | E

1969

new bearing tree

24 CEDAR 369W 41 1/2

scribed 1/4 S24 CE BT

NOTE THIS CORNER LIES 211 3 NORTH

of closing corner S1B, S19 T295 R1E and

50' south of left bank of S. Umpqua RIVER

D.M.  
S.W.B.

5/21/69

F.W.J.

W.R.P. JR.

Found corner

Var 20° to the East  
16

File No

54/82-66

DIETZGEN NO. 385.6