

Berenda

10/11

7265 R9W

Found

7" W Oak New 36" N59W 709°  
Tree show old ABC Felt I do  
not open probably rotted out

Also 3/4" Iron Pipe set by  
H. Boyer.

All things check with 1971 & 1935-38

Berenda

CS 30/38

Set Brass cap at 1/4 cor along side  
Iron Pipe NAD  
county Surveyors office

7265 R9W

1/4

S10/S11

1971

New Bearing Trees:

13" W Oak N 8 1/2 E 117°  
scribed 1/4 S11 CS BT

8" W Oak N 11 1/2 W 135°  
scribed 1/4 S10 CS BT

Note: This cor falls at fence cor  
fence running S-E-W.

O.K.  
J.W.D.

1-14-71

J.W.D.  
J.W.D.  
J.W.D.

#103

C. S. File No. 56/1-4

DIETZGEN NO. 385-6