

Renewal # 8

516/515

T215 R12W

Founds:

30" Spruce New Stump N80¹/₂W 308⁶/₆

opened for scribe "B"

36" Spruce New Stump S17W 235⁰/_R

Cor Falls in Middle of Road Fill, No Trace of I.P.P.e.

Renewal

Set 1" x 2.8" Iron P.P.e Set Flush with ground.

New Bearing object & Tree

Power Pole S17W 34⁶/₆

48" Spruce N80W 316⁶/₆

Scribed 1/4 516 CS BT

1-2-72

O.V.
J.W.B.

4762
457H

C.S. File No. 56/7-2

#32 ✓