

Renewal #15

22 | 23
27 | 26

T265 R2E

Found

9" D Fir S22E 213
Scribe visible

(Orig) 10" Yew dead S33W 330
Scribe visible

All other BTs down or stumps.

Also Brass cap out of ground MAR

G.L.O.

T265 R2E

22 | 23
27 | 26

1929

Renewal

Reset Brass cap at sec cor in
Mound of stone.

New Bearing Trees:

8" D Fir N58W 89
Scribed T265 R2E S 22 CS BT

9" D Fir N2E 96
Scribed T265 R2E S 23 CS BT

No Trees available to the SW

1-11-29

[Handwritten signature]

O.K.

[Handwritten signature]

#45 ✓

C.S. File No. 56/25-9

DIETZGEN NO. 385-B