

Renewal

$\frac{8}{17} \frac{9}{16}$

T 235 RBWA

Found

Orig BT's

30" Fir NW stump 553 $\frac{1}{2}$ W 31°

1958 BT's

39" F. STUMP N15W 27 $\frac{1}{2}$

Scribed T 235 RBW S 8 BT

50" Fir 579g N12E 150 $\frac{5}{8}$

Also Brass cap at sec. cor MKP

T 235 RBW

S 8 S 9

$\frac{517}{516}$

1958

Renewal

New Bearing Trees:

6" W. Fir 579E 18 $\frac{4}{8}$

Scribed 516 CS BT

6" D Fir N 50 E 11 $\frac{3}{8}$

Scribed 59 CS BT

DIETZGEN NO. 385-B

12" D. F.W

N42W

14²

scribed 7233 P8W S 0 CS BT

5" D. F.W

S3W

15²

scribed 517 CS BT

3-16-73

J 2 W D

J 2 W

J 2 C

OK
JL

10²

