

Renewal E $\frac{1}{16}$ $\frac{20}{29}$ 7213 P2W

Found

11" D. Fir NW 13" S7 $\frac{1}{4}$ E 23 $\frac{18}{10}$

shows good scar

NW Tree Down

Also Brass cap out of ground MKD.

B.L.M. U.S. Cads. Survey

E $\frac{1}{16}$ $\frac{520}{329}$

1964

DIETZGEN NO. 385-1-S

Renewal

Reset Brass cap at E $\frac{1}{16}$ 20W

New Bearing Tree

10" D Fir N70 W 19 $\frac{3}{10}$

Scribed E $\frac{1}{16}$ 520 CS BT

5-10-73

#199 ✓

C.S. File No. 56/25-19

[Signature]
REC
OK *[Signature]*