

Renewal

$\frac{28}{33}$

T28S R8W

Found

36" D. Fir now 43" S75E (Rec N75E) 9²

Bark scribe faint but visible

18" D. Fir now 31" S25W 30.4

Bark scribe visible $\frac{1}{4}$ BT

DIETZGEN NO. 385-5

Renewal: Using 2 dist + 1 Bearing I,
set Brass cap at $\frac{1}{4}$ cor MAD
county surveyors office

T28S R8W

$\frac{1}{4}$ $\frac{S28}{S33}$
1973

CS 56/25-27

22" D Fir S79W 4^W

scribed $\frac{1}{4}$ S33 CS BT

19" W Fir N4W 15^I

scribed $\frac{1}{4}$ S28 CS BT

OK *[Signature]*

3-13-73
[Signature]

#158