

Fd. O.K.T 295 R's 2 f3w

East  $\frac{1}{4}$  524 only - Fd, 1 $\frac{1}{4}$ "  
I.P. & B.T.s as Recorded in Ren,  
# 30, <sup>R.3W</sup> by J.M. Markham in 1957.  
The stone called for had Rolled  
about 10° ft. Down hill - we  
Reset cor Stone alongside  
I.P. - From this cor, The cor  
of Sec's  $\frac{119}{30}$  of T295 R2w Bears  
North 16° ft. and is 2 1917  
G.L.O. Brass cap & B.T.s in  
good cond. It is apparent  
that this cor. was not  
adequately searched for by  
the person who turned it  
in -

July 20, 1973

U.R.T.  
J.G.H.

Turned in by B.L.M.

✓ #7-729-2  
✓ #30-729-3

OK J.R.Q.

C. S. File No. 56/34-19