

Corner Renewal T235 R9W 23 | 24  
26 | 25

Found

ORIGINAL CORNER STONE 20" x 8" x 4"  
ONE NOTCH ON EAST FACE AND  
TWO NOTCHES ON SOUTH FACE

ORIGINAL BEARING TREES FOUND

30" NOW 50" FIR BEARS N24°W  
68' (REC. 792)

BARK SCRIBED

"T235 R9W S23 BT"

A ROTTED STUMP BEARS N61°E

12' FEET. BARK IS GONE NO

SCRIBING VISIBLE

OTHER BEARING TREES ORIGINALLY  
RECORDED, NOT FOUND.

RENEWAL

SET BRASS CAP AT SECTION

CORNER MARKED

COUNTY SURVEYORS OFFICE

T235 R9W

S23	S24
S26	S25

#67 ✓

C. S. File No. 56/39-161973

(100)

NEW BEARING TREES

—  
ALL OF THE FOLLOWING TREES  
USED FOR BEARING TREES TAGGED  
WITH B.L.M. TAGS SET  
8/13/69 BY TS, CS

NO SCRIBING FOUND.

—  
10" FIR BEARS S 47° E 16<sup>3</sup>' (TAG READS 15<sup>9</sup>)

SCRIBED T235 R9W S25 BT

16" FIR BEARS N 30° E 18<sup>9</sup>

(TAGGED N 28° E 18<sup>2</sup>)

SCRIBED T235 R9W S24 CS BT

30" FIR BEARS S 74° W 21<sup>2</sup>

(TAGGED S 75° W 20<sup>4</sup>)

SCRIBED T235 R9W S26 CS BT

CORNER IS 50' BELOW AND ON  
THE SOUTH SIDE OF A NE SLOPING

FILED

RECEIVED

NOV 6/1978

PLE  
*[Signature]*

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

OK  
*[Signature]*