

1-24-74

$\frac{1}{4}$ $\frac{4}{9}$ T235 R9W

FD:

ORIG. 6" NOW 16" D. FIR SNAG, ROTTEN AND SHOWING GOOD SCARS ON NORTH AND SOUTH FACES. I OPEN AND FIND SCRIBING " $\frac{1}{4}$ S" ON NORTH FACE AND NO SCRIBING ON SOUTH FACE.

FROM WHICH

ORIG. 12" NOW 24" D. FIR SNAG, ROTTEN, BEARS N 12° E 4 $\frac{3}{4}$ FEET (REC. NORTH 4 $\frac{1}{2}$ FT) WITH PARTIAL SCRIBES VISIBLE. I OPEN COMPLETELY AND FIND SCRIBING " $\frac{1}{4}$ S 3 BT" THE "3" IN THE SCRIBE DOES NOT CORRESPOND WITH THE FIELD NOTES

12" D. FIR SNAG, ROTTEN BEARS S 23° E 5 $\frac{1}{2}$ FT (REC. S 28° E 3 $\frac{3}{4}$ FT) SCRIBED AREA DECAYED AND FALLEN.

#10 ✓

PAGE I
C. S. File No. 56/43-9 ✓

FROM THIS LOCATION AN OLD LINE
OF BLAZES EXTENDS TO THE EAST AND
A SMALL POND IS LOCATED AS CALLED
FOR TO THE WEST.

I REMOVE THE DETERIORATING ORIG.
CORNER TREE AND SET BRASS CAP
MARKED:

COUNTY SURVEYORS OFFICE

T 23 S

$\frac{1}{4}$ $\frac{34}{39}$

R 9 W

1974

FROM WHICH

26" * D. FIR BEARS S 39° E - 45⁵ FT.
SCRIBED $\frac{1}{4}$ S 9 CS BT

22" D. FIR BEARS N 40° E 70² FT.
SCRIBED $\frac{1}{4}$ S 4 CS BT

1-24-74
S.L.L.
P.L.E.
OK [Signature]