

6-27-74

$\frac{23}{26} \frac{1}{4}$

T305 RBW

(REN. # 9 & 22)

FD

12" FIR STUMP WITH POSSIBLE SCRIBED AREA CHOPPED AWAY. ALSO FOUND A  $1\frac{1}{4}$ " I. PIPE SET ON NORTHERLY EDGE OF STUMP, FROM WHICH:

52" FIR STUMP BEARS  $S 45^{\circ} E 6^{\frac{1}{2}}$  TO CENTER OF STUMP,  $3\frac{1}{2}$  TO APPARENT FACE OF STUMP. ORIG. NOTES INDICATE A 46" FIR AT RECORD MEASUREMENT  $S 31^{\circ} E 3\frac{3}{4}$  FT. THIS STUMP BADLY BURNT.

27" FIR STUMP BEARS  $N 1\frac{1}{2}^{\circ} E 50^{\frac{6}{10}}$  FT, (REC.  $N 1\frac{1}{2}^{\circ} E 49^{\frac{7}{10}}$  FT) SCRIBED  $\frac{1}{4}$  S BT S. 23"

20" FIR STUMP BEARS  $S 50^{\circ} W 96^{\frac{1}{4}}$  FT, SCRIBED  $\frac{1}{4}$  S BT SEC 26"

WE SET A STEEL FENCEPOST WITH SURVEY MARKER - WITNESS SIGN ATTACHED ALONGSIDE CORNER STUMP.

6-27-74

THERE ARE NO TREES NEAR.

Gary Langley

PETER EARLE C

#113 ✓

C. S. File No. 56/51-27 OK