

T285

7-22-74

$\frac{1}{4}$  34  
3 R2E

T295

FD:

IRON PIPE, FIRMLY SET, PROTRUDING

6" ABOVE GROUND LEVEL WITH BRASS

CAP ATTACHED, MARKED:

U.S. GENERAL LAND OFFICE SURVEY

$\frac{1}{4}$  S 34  
S 3  
1921

FROM WHICH:

AN ORIG 16", NOW 20" D. FIR BEARS

N81°W 15<sup>2</sup> FT, WELL-HEALED.

#2 T28-1E ✓  
#69 T29-1E ✓

J. S. File No. 57/2-4 Page 1  
C

DIETZGEN NO. 385-5

Now Fr 22<sup>nd</sup> BT

S 5° W

26<sup>th</sup> LVL

$\frac{1}{4}$  S 3 CS BT

A STUMP HOLE WITH FRAGMENTS OF  
MADRONE ROOTS BEARS S 31° W  
5<sup>9</sup> FT., THE REMAINDER OF THE TREE  
IS GONE.

WE MARK A NEW BEARING TREE:

A 22" D. FIR BEARS S 5° W  
26<sup>3</sup> FT., SCRIBED "1/4 S 3 CS BT"

THIS CORNER LIES APPROX 75 FT WEST  
OF AND 30 FT. BELOW AN ALL-WEATHER  
LOGGING ROAD.

7-22-74

Larry Langley  
P.L.E.

OK  
*[Signature]*