

11-5-74

5 | 4

T32 S R6W

1/4

FD:

TWO ORIGINAL BEARING TREES:

AN ORIG. 30" NOW 10" D. FIR BEARING N 30° E

17 1/2 FT. WE FIND A FAINT "BT" SCRIBED IN

THE BARK - THERE IS ALSO A "1/4" CHOPPED IN

THE BARK BUT IT IS NOT AN ORIGINAL MARKING.

AN ORIG. 20" NOW 34" D. FIR BEARING N 15° W

22 1/2 FT. WE FIND FAINT BARK SCRIBING

"1/4 BT".

AT THE CORNER POINT, WE SET A 1" X 30" IRON

PIPE WITH BRASS CAP ATTACHED & MARKED:

COUNTY SURVEYOR'S OFFICE

T32 S

SE | SE

1/4

139 ✓

U. S. File No. 57/12-2 R6W
1974

PAGE 1

U

DIETZGEN NO. 385-6

20⁶@24^{1/2}°

.90996

18⁷

25²@30°

.86603

21⁸

24³@28°

.88295

21⁴

19°@22°

.92718

17⁶

SW BT 30" D. FR

S 53° W

B3⁵ LVL

1/4 S S CSBT

SE BT

12" YEW

37²@16°

.9613

36²

S 74° E

1/4 S S CSBT

90 TO STUMP

21

42

FROM WHICH WE MARK THE FOLLOWING BT'S:

A 30" D. FIR BEARS S 53° W 33 ⁵/₁₆ FT.,
SCRIBED "1/4 S 5 CSBT".

A 12" YEW BEARS S 74° E 36 ⁷/₁₆ FT.,
SCRIBED "1/4 S 4 CSBT".

COMPASS DECLINATION SETTING: 20° EAST.

11-5-74

Darryl J. Knight
PETER L. EARLE

OK
~~all~~