

4-22-75

RENEWAL

T235

RLW      R5W

S36      S31

S1      S6

T245

FOUND

USGLD BRASS

CAP STAMPED AS NOTED ABOVE, (1943)

B.T.s

50" FIR STUMP WITH GOOD SCAR

BEARS N 58° E 43<sup>8</sup> FEET (REC N 57 1/2° E 39.6')

38" FIR STUMP BLAZED - SCAR ROTED

BEARS S 59° E 83<sup>8</sup> FEET (REC. S 62 1/2° E 83.8')

36" FIR STUMP BLAZED - SOME SCRIBING

VISIBLE, BLAZED AREA MAINLY ROTED

BEARS S 18° W 119<sup>8</sup> FEET (REC S 18 1/2° W 116.8')

48" FIR BLOWN DOWN BLAZED

BEARS N 84 1/2° W      (REC. N 82 1/2° W 184.8)

DISTANCE. INDETERMINATE

#165 - T236  
#99 - T235  
#111 - T246  
#88 - T245

G.S. File No. 57/21-10

DIETZGEN NO. 3855-6

RENEWAL

A 9" DIA FIR BEARS N 46° W 30<sup>2</sup> FT

SCRIBED "T 23 S R 6 W S 36 CS BT"

A 30" DIA FIR BEARS N 85° E 30<sup>2</sup> FT

SCRIBED "T 23 S R 5 W S 31 CS BT"

A 16" DIA FIR BEARS S 7<sup>1</sup>/<sub>2</sub>° E 66<sup>2</sup> FT.

SCRIBED "T 24 S R 5 W S 6 CS BT"

DIST 67<sup>2</sup> @ -13° =

A 10" DIA FIR BEARS S 57° W 27<sup>1</sup> FT.

SCRIBED "T 24 S R 6 W S 1 CS BT"

CORNER LIES IN WOODED AREA (MADRONE

& FIR) IS LOCATED AT INTERSECTION

OF FENCE RUNNING SOUTHERLY,

EASTERLY, & WESTERLY.

4-22-75

L.E. MONREAN

M.V. CANGIE

OK  
*[Signature]*