

7-10-75

$\frac{1}{4} \frac{6}{7}$  T23S R4W

(SEE REN# 28)

Fd:

TWO IRON BARS SUPPORTED IN A MOUND OF ROCK, LOCATED IN AN OLD E-W FENCE

FROM WHICH:

AN 18" NOW 24" D. FIR MARKED IN 1957 BY THE COUNTY SURVEYOR BEARS S 35° E, 29<sup>B</sup> FT., ALIVE AND IN GOOD CONDITION.

WE FIND NO EVIDENCE OF ANY OTHER CORNER ACCESSORIES. WE DO NOT SET A NEW MONUMENT DUE TO VERY SHALLOW SOIL.

WE MARK THE FOLLOWING NEW BEARING TREE;

AN 11" D. FIR BEARS N 35° E 26<sup>S</sup> FT., SCRIBED "1/4 S6 CS BT" ON A DOUBLE BLAZE.

COMPASS DECLINATION: 20° EAST.

#151 T23-4<sup>th</sup> OK *[Signature]*

7-10-75

CS 57/89-4

*[Signature]*  
CLELL E. GOODWIN  
M. LENORA LADIG

DIETZEN NO. 365-S

11" DF

N 35°E

27<sup>3</sup>@ 13°

.9744

26<sup>6</sup>

" 1/4 S 6 CSBP

