

T 305 R3W
S11 S12
S14 S13

RENEWAL

SEE RENEWAL # 125
FOUND

BRASS CAP SET BY

1. BYRON IN 1963 STAMPED
"COUNTY SURVEYORS OFFICE"

T 305
S11 S12
S14 S13
R3W
1963

CAP IS OUT OF GROUND AND DOWNHILL FROM SECTION CORNER POSITION.

2. A FIR 28 (NOW 44) INCHES DIAMETER BEARS S 66 3/4° W, 17² FEET. TREE HAS GOOD BLAZE,

3. A FIR 13 (NOW 29) INCH DIAMETER BEARS N 38 1/4° W, 8⁶ FEET. TREE HAS GOOD BLAZE, I OPEN PARTIALLY AND FIND SCRIBING "T305".

RENEWAL

RESET BRASS CAP AT SECTION CORNER

1. CAP IS MARKED AS NOTED.

✓ W

C. S. File No. 57/39-45

#205

RENEWAL

AS NE AND SE BEARING TREES
ARE GONE I SCRIBE TWO NEW
BEARING TREES.

2. A RED CEDAR 8 INCH DIAM. BEARS
N $3\frac{1}{2}^{\circ}$ E, 79 ⁶ FEET. TREE IS DOUBLE
BLAZED AND SCRIBED "T30S R3W
S12 CS BT",

3. A HEMLOCK 22 INCH DIAMETER BEARS
S $7\frac{1}{2}^{\circ}$ E, 21 ⁹ FEET. TREE IS
DOUBLE BLAZED AND SCRIBED
"T30S R3W S13 CS BT".

MAG. DEC. 20^oE

12-23-75

L. E. MONREAN

P. L. E.

J. H. C.

OK
JHL