

FILED
RECEIVED ✓

OCT 7 1974

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.



Weyerhaeuser Company

Map No. 389
Southwest Oregon Region
North Bend, Oregon 97459
(503) 756-5121 *Map No. 389*

October 4, 1974

Douglas County Surveyor
Douglas County Court House
Roseburg, Oregon 97470

Attn: Virginia A. Yates

Following is the information you requested in your letter dated 9-18-74 in reference to the 1/4 corner between Sections 32 and 33 of Township 25 South, Range 8 West.

This corner was set by transit and chain survey using the broken boundary rule because of the double section corners to the north.

The corner information is as follows:

1-1/2" x 3' galvanized iron pipe with brass cap marked
"T 25S - R 8W 1/4 cor 32/33."

A 28" red cedar N77° 30' E 29.0 ft. (H.D.) scribed 1/4 S B.T. and further marked with Weyerhaeuser tag and galvanized spike in root collar.

An 18" red cedar N76-1/2 W 54.0 ft (H.D.) scribed 1/4 S B.T. and further marked with a Weyerhaeuser tag and galvanized spike in the root collar.

The reason this information had not been sent to you sooner is because it was a part of an uncompleted survey to set the 1/4 of Section 32. We had some personnel changes as well as priorities and the completion was delayed. I understood that this work is now being completed by the B.L.M. although we have not enjoyed the courtesy of being informed of their plans.

Sincerely,

WEYERHAEUSER COMPANY

Henry R. Reppeto
Region Engineer

HRR/cd

cc: T. J. Orr

#82 ✓



COUNTY OF DOUGLAS
OFFICE OF THE SURVEYOR
ROSEBURG, OREGON 97470

September 18, 1974

Henry Repetto
Weyerhaeuser Company
Airport Way
Coos Bay, OR 97420

Dear Mr. Repetto:

Our office has had an inquiry of a corner found in the field but no evidence filed with this office pertaining to it.

It is the 1/4 Corner for Sections 32 and 33 of T. 25 S., R. 8 W. A brass cap with a Weyco mark and two bearing trees with yellow tags were found.

Could you give any information concerning this corner and any other that would be of value to us.

Thank you,

Virginia A. Yates
Office Supervisor

(CORNER FD BY BLM)