


M 93-10

October 11, 1982



Richard J. Hintz
Professional Land Surveyor

1890 N. 14th Street • Coos Bay, Oregon • 97420 • (503) 267-3806

FILED
RECEIVED *RF*
OCT 13 1982
COUNTY SURVEYOR
DOUGLAS COUNTY, OREGON

Francis L. Ingram
County Surveyor
Justice Building
Roseburg, Oregon 97470

Dear Sir:

This narrative is submitted in conjunction with my survey map for International Paper Company in Sections 6 and 8, Township 21 South, Range 11 West of the Willamette Meridian.

I rotated the bearing on Survey CS 54/15 between the W.C. W/16 corner for Sections 8 and 17 and the W1/16 corner position by 0° 12' 34" to the right. This rotation was determined by calculating an inverse from my survey between the South 1/4 corner and the Southwest corner of said Section 8, (North 88° 10' 36" West) and then comparing this with Survey CS 54/15 (North 88° 23' 10" West), resulting in the difference 0° 12' 34".

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Richard J. Hintz

OREGON
MAY 18, 1980
RICHARD J. HINTZ
497