

Corner Renewal

1/4 cor Sec $\frac{12}{13}$ T25S R2W

Found: Cadastral BC under

10 inches of dirt + Rock, with
steel fence post along side
39" Fir stump - S54W 12 $\frac{1}{2}$ ft
16" Hemlock South 28 $\frac{1}{2}$ ft. Broken off
at the stump.

SURVEY SHEET 1168

Scribed

5" D. Fir N89W 24 $\frac{1}{2}$ ft

5" D. Fir S20E 39 $\frac{1}{2}$ ft.

Brass disc on each face with RLS 498"
Cor sets along side a small
dry stream bed - entire area is
covered with 1-4 feet of dirt and
rock that has washed in from above

Howard W. Johnston
PLS 498
Feb 5, 1982

#117 725-2

G.S. File No. 58/188-6